Providing
**C** CRANE SERVICES.
**H** HEIGHT SAFETY.
**L** LIFTING SERVICES.
**E** ENGINEERING.

# *Lifting Gear Inspection Report*

| | |
|---|---|
| Job No: | 24-0031 |
| Page No | |
| Client Order/Purchase No: | |
| Date: | Start: 02-Feb-24 Finish: |
| Site: | Multipule |

Inspectors
N Thompson NT
D Simpkins DS
C Bisa CB


Dianneil Pty Ltd. t/as CHLE
ABN: 73 619 705 190
PO Box 454, Mitchell, ACT 2911
Ph: (02) 6255 5741
Email: chlesales@chle.com.au


Client name: …
Address:……..
Contact:……
Email:……..
Mob: ……

**RAR CRANES**
36 Bedford street
Queanbeyan NSW 2620
Richard Garrety
richard@rargroup.com.au
0405 991 935

**NOTE:** The Next Inspection Due Date is a Maximum Date Due. The inspection schedule has to be determined by the end user based on the duty cycle (of M3 as specified in AS1418.1) and the environmental conditions of use

| Location | Asset | Inspection Date | Serial No | Description | Manufacturer | WLL | Inspected IAW: AS | Passed | Failed | Missing | Repaired | Condemned | Inspector | Next Inspection Due | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 970 | | 13-Feb-24 | J709 | G120 10mm x 6M 2Leg chain sling c/w eye grab and clevis safety hooks | Allways Rigging Gear | 8.6t @ 60° | AS 3775 | YES | | | | | CB | 13-Feb-25 | |
| 970 | | 13-Feb-24 | J710 | G120 10mm x 6M 2Leg chain sling c/w eye grab and clevis safety hooks | Allways Rigging Gear | 8.6t @ 60° | AS 3775 | YES | | | | | CB | 13-Feb-25 | |
| 970 | | 13-Feb-24 | F916 | G100 16mm x 6M 2Leg chain sling c/w eye grab and clevis safety hooks | Allways Rigging Gear | 17.3t @ 60° | AS 3775 | YES | | | | | CB | 13-Feb-25 | |
| 970 | | 13-Feb-24 | F917 | G100 16mm x 6M 2Leg chain sling c/w eye grab and clevis safety hooks | Allways Rigging Gear | 17.3t @ 60° | AS 3775 | YES | | | | | CB | 13-Feb-25 | |
| 970 | | 09-Mar-23 | 3A-675 | Swivel Panel Lifter | Reid | 5t | AS 3580 | YES | | | | | NT | 09-Mar-24 | |
| 970 | | 09-Mar-23 | 3A-704 | Swivel Panel Lifter | Reid | 5t | AS 3580 | YES | | | | | NT | 09-Mar-24 | |
| 970 | | 09-Mar-23 | 9F-462 | Swivel Panel Lifter | Reid | 5t | AS 3580 | YES | | | | | NT | 09-Mar-24 | |
| 970 | | 09-Mar-23 | 6F-92 | Swivel Panel Lifter | Reid | 5t | AS 3580 | YES | | | | | NT | 09-Mar-24 | |
| 970 | | 09-Mar-23 | PH-0618-11 | Swivel Panel Lifter | Phillips | 2.5t | AS 3580 | YES | | | | | NT | 09-Mar-24 | |
| 970 | | 09-Mar-23 | PH-0584-11 | Swivel Panel Lifter | Phillips | 2.5t | AS 3580 | YES | | | | | NT | 09-Mar-24 | |
| 970 | | 09-Mar-23 | 2D-428 | Swivel Panel Lifter | Reid | 2.5t | AS 3580 | YES | | | | | NT | 09-Mar-24 | |
| 970 | | 09-Mar-23 | 7G-73 | Swivel Panel Lifter | Reid | 2.5t | AS 3580 | YES | | | | | NT | 09-Mar-24 | |
| 970 | | 09-Mar-23 | 184 | Swivel Panel Lifter | QLR | 1.3t | AS 3580 | YES | | | | | NT | 09-Mar-24 | |
| 970 | | 09-Mar-23 | 7189-1-1116 | Swivel Panel Lifter | Austlift | 1.3t | AS 3580 | YES | | | | | NT | 09-Mar-24 | |
| 970 | | 09-Mar-23 | D&DCR2 | Swivel Panel Lifter | AC Tech | 1.3t | AS 3580 | YES | | | | | NT | 09-Mar-24 | |
| 970 | | 09-Mar-23 | BS-7110 | Swivel Panel Lifter | Reid | 1.3t | AS 3580 | YES | | | | | NT | 09-Mar-24 | |
| 970 | | 13-Feb-24 | 1500005.04 | 3M Spreader Bar 2 Lift Pionts | Terex | 15T | AS 3775 | YES | | | | | CB | 13-Feb-25 | |
| | | | | | | | | | | | | | | 31-Dec-00 | |
| | | | | | | | | | | | | | | 31-Dec-00 | |
| | | | | | | | | | | | | | | 31-Dec-00 | |
| | | | | | | | | | | | | | | 31-Dec-00 | |
| | | | | | | | | | | | | | | 31-Dec-00 | |
| | | | | | | | | | | | | | | 31-Dec-00 | |
| | | | | | | | | | | | | | | 31-Dec-00 | |
| | | | | | | | | | | | | | | 31-Dec-00 | |
| | | | | | | | | | | | | | | 31-Dec-00 | |
| | | | | | | | | | | | | | | 31-Dec-00 | |
| | | | | | | | | | | | | | | 31-Dec-00 | |
| | | | | | | | | | | | | | | 31-Dec-00 | |
| | | | | | | | | | | | | | | 31-Dec-00 | |

| | | | | | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | | | | | | | | | | 31-Dec-00 | |
| | | | | | | | | | | | | | | 31-Dec-00 | |
| | | | | | | | | | | | | | | 31-Dec-00 | |
| | | | | | | | | | | | | | | 31-Dec-00 | |
| | | | | | | | | | | | | | | 31-Dec-00 | |
| | | | | | | | | | | | | | | 31-Dec-00 | |
| | | | | | | | | | | | | | | 31-Dec-00 | |
| | | | | | | | | | | | | | | 31-Dec-00 | |
| | | | | | | | | | | | | | | 31-Dec-00 | |
| | | | | | | | | | | | | | | 31-Dec-00 | |
| | | | | | | | | | | | | | | 31-Dec-00 | |
| | | | | | | | | | | | | | | 31-Dec-00 | |
| | | | | | | | | | | | | | | 31-Dec-00 | |
| | | | | | | | | | | | | | | 31-Dec-00 | |
| | | | | | | | | | | | | | | 31-Dec-00 | |
| | | | | | | | | | | | | | | 31-Dec-00 | |
| | | | | | | | | | | | | | | 31-Dec-00 | |
| | | | | | | | | | | | | | | 31-Dec-00 | |
| | | | | | | | | | | | | | | 31-Dec-00 | |
| | | | | | | | | | | | | | | 31-Dec-00 | |
| | | | | | | | | | | | | | | 31-Dec-00 | |
| | | | | | | | | | | | | | | 31-Dec-00 | |
| | | | | | | | | | | | | | | 31-Dec-00 | |
| | | | | | | | | | | | | | | 31-Dec-00 | |
| | | | | | | | | | | | | | | 31-Dec-00 | |
| | | | | | | | | | | | | | | 31-Dec-00 | |
| | | | | | | | | | | | | | | 31-Dec-00 | |
| | | | | | | | | | | | | | | 31-Dec-00 | |
| | | | | | | | | | | | | | | 31-Dec-00 | |
| | | | | | | | | | | | | | | 31-Dec-00 | |
| | | | | | | | | | | | | | | 31-Dec-00 | |
| | | | | | | | | | | | | | | 31-Dec-00 | |
| | | | | | | | | | | | | | | 31-Dec-00 | |
| | | | | | | | | | | | | | | 31-Dec-00 | |
| | | | | | | | | | | | | | | 31-Dec-00 | |
| | | | | | | | | | | | | | | 31-Dec-00 | |
| | | | | | | | | | | | | | | 31-Dec-00 | |
| | | | | | | | | | | | | | | 31-Dec-00 | |
| | | | | | | | | | | | | | | 31-Dec-00 | |
| | | | | | | | | | | | | | | 31-Dec-00 | |
| | | | | | | | | | | | | | | 31-Dec-00 | |
| | | | | | | | | | | | | | | 31-Dec-00 | |
| | | | | | | | | | | | | | | 31-Dec-00 | |
| | | | | | | | | | | | | | | 31-Dec-00 | |