

# INSPECTION REPORT



**COMPANY NAME:** RAR Cranes Australia Pty Ltd **DATE PRINTED:** 29/03/2021  
**ADDRESS:** 36 Bedford St, Queanbeyan, NSW, 2620. **ACCOUNT NUMBER:** 6765  
**LOCATION:** Unit 481 **SALES ORDER:** 103487  
**LEAD INSPECTOR:** Gary Barreto  
**SIGNATURE:**




---

Inspection Date	Serial #	Description	Passed	Failed	Missing	Repaired	Condemned	New Into Service	Next Inspection Due
07/03/2021	F4862	10mm x 6m x 2leg G80 Chain Sling Complete With Shorteners & Self Locking Hooks	✓						07/03/2022
07/03/2021	M1366	10mm x 6m x 2leg G80 Chain Sling Complete With Shorteners & Self Locking Hooks	✓						07/03/2022
07/03/2021	D1888	13mm x 4m x 2leg G80 Chain Sling Complete With Shorteners & Self Locking Hooks	✓						07/03/2022
07/03/2021	844	16mm x 1m x 1leg G80 Chain Sling Complete With Shorteners & Self Locking Hooks	✓						07/03/2022
07/03/2021	E3898	8mm x 4m x 2leg G80 Chain Sling Complete With Shorteners & Self Locking Hooks	✓						07/03/2022
07/03/2021	D381	13mm x 4m x 2leg G80 Chain Sling Complete With Shorteners & Self Locking Hooks	✓						07/03/2022
07/03/2021	RAR8	Container Lifter Left Hand	✓						07/03/2022



NATA #18983



FIRST FULL MEMBER

LEEA #1192

# INSPECTION REPORT



Inspection Date	Serial #	Description	Passed	Failed	Missing	Repaired	Condemned	New Into Service	Next Inspection Due
07/03/2021	0618-11	2.5t Clutch Lifter	✓						07/03/2022
07/03/2021	RAR2	Container Lifter Right Hand	✓						07/03/2022
07/03/2021	RAR1	Container Lifter Right Hand	✓						07/03/2022
08/03/2021	150786	3M Spreader Beam 2 Lift Points	✓						08/03/2022
07/03/2021	7G73	2.5t Clutch Lifter	✓						07/03/2022
07/03/2021	06075-2-0864	2.5t Clutch Lifter	✓						07/03/2022
07/03/2021	06075-2-0606	2.5t Clutch Lifter	✓						07/03/2022
07/03/2021	2D428	2.5t Clutch Lifter	✓						07/03/2022
07/03/2021	818	2.5t Clutch Lifter	✓						07/03/2022
07/03/2021	8S737	1.3t Clutch Lifter	✓						07/03/2022
07/03/2021	7189-1-454	1.3t Clutch Lifter	✓						07/03/2022



NATA #18983



FIRST FULL MEMBER

LEEA #1192