

INSPECTION REPORT



COMPANY NAME: RAR Cranes Australia Pty Ltd **DATE PRINTED:** 29/03/2021
ADDRESS: 36 Bedford St, Queanbeyan, NSW, 2620. **ACCOUNT NUMBER:** 6765
LOCATION: Unit 910 **SALES ORDER:** 103487
LEAD INSPECTOR: Gary Barreto
SIGNATURE:



Inspection Date	Serial #	Description	Passed	Failed	Missing	Repaired	Condemned	New Into Service	Next Inspection Due
07/03/2021	P2041	10mm x 8m x 2leg G100 Chain Sling Complete With Shorteners & Self Locking Hooks	✓						07/03/2022
07/03/2021	P2011	16mm x 8m x 2leg G100 Chain Sling Complete With Shorteners & Self Locking Hooks	✓						07/03/2022
07/03/2021	P2040	16mm x 8m x 2leg G100 Chain Sling Complete With Shorteners & Self Locking Hooks	✓						07/03/2022
07/03/2021	P1919	10mm x 8m x 2leg G100 Chain Sling Complete With Shorteners & Self Locking Hooks	✓						07/03/2022
07/03/2021	24685	16mm x 8m x 2leg G80 Chain Sling Complete With Shorteners & Self Locking Hooks	✓						07/03/2022
07/03/2021	R0735	10mm x 6m x 2leg G80 Chain Sling Complete With Shorteners & Self Locking Hooks	✓						07/03/2022
08/03/2021	ALS10748	4m Spreader Beam 2 Lift Points	✓						08/03/2022



NATA #18983



FIRST FULL MEMBER

LEEA #1192