

# INSPECTION REPORT



**COMPANY NAME:** RAR Cranes Australia Pty Ltd **DATE PRINTED:** 29/03/2021  
**ADDRESS:** 36 Bedford St, Queanbeyan, NSW, 2620. **ACCOUNT NUMBER:** 6765  
**LOCATION:** Unit 930 **SALES ORDER:** 103487  
**LEAD INSPECTOR:** Gary Barreto  
**SIGNATURE:**




---

Inspection Date	Serial #	Description	Passed	Failed	Missing	Repaired	Condemned	New Into Service	Next Inspection Due
07/03/2021	519	16mm x 6m x 2leg G100 Chain Sling Complete With Shorteners & Self Locking Hooks	✓						07/03/2022
07/03/2021	518	16mm x 6m x 2leg G100 Chain Sling Complete With Shorteners & Self Locking Hooks	✓						07/03/2022
07/03/2021	517	13mm x 6m x 2leg G100 Chain Sling Complete With Shorteners & Self Locking Hooks	✓						07/03/2022
07/03/2021	130.15	13mm x 6m x 2leg G80 Chain Sling Complete With Shorteners & Self Locking Hooks	✓						07/03/2022
07/03/2021	249	10mm x 6m x 2leg G80 Chain Sling Complete With Shorteners & Self Locking Hooks	✓						07/03/2022
07/03/2021	J369	10mm x 8m x 2leg G80 Chain Sling Complete With Shorteners & Self Locking Hooks	✓						07/03/2022
07/03/2021	516	13mm x 6m x 2leg G100 Chain Sling Complete With Shorteners & Self Locking Hooks	✓						07/03/2022



NATA #18983



FIRST FULL MEMBER

LEEA #1192

# INSPECTION REPORT



Inspection Date	Serial #	Description	Passed	Failed	Missing	Repaired	Condemned	New Into Service	Next Inspection Due
07/03/2021	M1191	10mm x 8m x 2leg G80 Chain Sling Complete With Shorteners & Self Locking Hooks	✓						07/03/2022



NATA #18983



LEEA #1192