

INSPECTION REPORT



COMPANY NAME: RAR Cranes Australia Pty Ltd **DATE PRINTED:** 29/03/2021
ADDRESS: 36 Bedford St, Queanbeyan, NSW, 2620. **ACCOUNT NUMBER:** 6765
LOCATION: Unit 937 **SALES ORDER:** 103487
LEAD INSPECTOR: Gary Barreto
SIGNATURE:



Inspection Date	Serial #	Description	Passed	Failed	Missing	Repaired	Condemned	New Into Service	Next Inspection Due
07/03/2021	181321	13mm x 8m x 2 Leg G100 Chain Sling Complete With Shortners And Self Locking Hooks	✓						07/03/2022
08/03/2021	1500831	3m Spreader Beam 2 Lift Points	✓						08/03/2022
07/03/2021	181320	13mm x 8m x 2 Leg G100 Chain Sling Complete With Shortners And Self Locking Hooks	✓						07/03/2022
07/03/2021	181318	10mm x 8m x 2 Leg G100 Chain Sling Complete With Shortners And Self Locking Hooks	✓						07/03/2022
07/03/2021	181319	10mm x 8m x 2 Leg G100 Chain Sling Complete With Shortners And Self Locking Hooks	✓						07/03/2022



NATA #18983



FIRST FULL MEMBER

LEEA #1192