

INSPECTION REPORT



COMPANY NAME: RAR Cranes Australia Pty Ltd **DATE PRINTED:** 29/03/2021
ADDRESS: 36 Bedford St, Queanbeyan, NSW, 2620. **ACCOUNT NUMBER:** 6765
LOCATION: Unit 949 **SALES ORDER:** 103487
LEAD INSPECTOR: Gary Barreto
SIGNATURE:



Inspection Date	Serial #	Description	Passed	Failed	Missing	Repaired	Condemned	New Into Service	Next Inspection Due
07/03/2021	F3796	16mm x 8m x 2leg G80 Chain Sling Complete With Shorteners & Self Locking Hooks	✓						07/03/2022
07/03/2021	0417	16mm x 6m x 2leg G80 Chain Sling Complete With Shorteners & Self Locking Hooks	✓						07/03/2022
07/03/2021	0085	1.3t Clutch Lifter	✓						07/03/2022
07/03/2021	06075-1-2401	1.3t Clutch Lifter	✓						07/03/2022
07/03/2021	A305	10mm x 6m x 2leg G120 Chain Sling Complete With Shorteners & Self Locking Hooks	✓						07/03/2022
07/03/2021	A306	10mm x 6m x 2leg G120 Chain Sling Complete With Shorteners & Self Locking Hooks	✓						07/03/2022
07/03/2021	B3	Container Lifter Left Hand	✓						07/03/2022



NATA #18983



FIRST FULL MEMBER

LEEA #1192

INSPECTION REPORT



Inspection Date	Serial #	Description	Passed	Failed	Missing	Repaired	Condemned	New Into Service	Next Inspection Due
07/03/2021	B4	Container Lifter Left Hand	✓						07/03/2022
07/03/2021	B1	Container Lifter Right Hand	✓						07/03/2022
07/03/2021	B2	Container Lifter Right Hand	✓						07/03/2022
07/03/2021	5D27	2.5t Clutch Lifter	✓						07/03/2022
07/03/2021	PH-348	2.5t Clutch Lifter	✓						07/03/2022
07/03/2021	6G482	2.5t Clutch Lifter	✓						07/03/2022
07/03/2021	1286	2.5t Clutch Lifter	✓						07/03/2022
07/03/2021	8F314	5t Clutch Lifter	✓						07/03/2022
07/03/2021	6F712	5t Clutch Lifter	✓						07/03/2022
07/03/2021	8F221	5t Clutch Lifter	✓						07/03/2022
07/03/2021	5F839	5t Clutch Lifter	✓						07/03/2022
07/03/2021	014	1.3t Clutch Lifter	✓						07/03/2022
07/03/2021	187	1.3t Clutch Lifter	✓						07/03/2022
08/03/2021	159282-5	3m Spreader Beam 2 Lift Points	✓						08/03/2022



NATA #18983



FIRST FULL MEMBER

LEEA #1192