

INSPECTION REPORT



COMPANY NAME: RAR Cranes Australia Pty Ltd **DATE PRINTED:** 29/03/2021
ADDRESS: 36 Bedford St, Queanbeyan, NSW, 2620. **ACCOUNT NUMBER:** 6765
LOCATION: Unit 980 **SALES ORDER:** 103487
LEAD INSPECTOR: Gary Barreto
SIGNATURE:



Inspection Date	Serial #	Description	Passed	Failed	Missing	Repaired	Condemned	New Into Service	Next Inspection Due
07/03/2021	19440	10mm x 8m x 2leg G80 Chain Sling Complete with Oversized Heading, Shorteners and Self Locking Hooks	✓						07/03/2022
07/03/2021	19445	10mm x 8m x 2leg G80 Chain Sling Complete with Oversized Heading, Shorteners and Self Locking Hooks	✓						07/03/2022
07/03/2021	6870W	13mm x 8.4m x 2leg G80 Chain Sling Complete With Shorteners & Self Locking Hooks	✓						07/03/2022
07/03/2021	ALS1477.1	16mm x 8.5m x 2leg G100 Chain Sling Complete With Shorteners & Self Locking Hooks	✓						07/03/2022
07/03/2021	ALS1477.2	16mm x 8.8m x 2leg G100 Chain Sling Complete With Shorteners & Self Locking Hooks	✓						07/03/2022



NATA #18983



FIRST FULL MEMBER

LEEA #1192

INSPECTION REPORT



Inspection Date	Serial #	Description	Passed	Failed	Missing	Repaired	Condemned	New Into Service	Next Inspection Due
07/03/2021	C6.4	13mm x 6.5m x 2leg G80 Chain Sling Complete With Shorteners & Self Locking Hooks	✓						07/03/2022
08/03/2021	156288-05	3m Spreader Beam 2 Lift Points	✓						08/03/2022



NATA #18983



LEEA #1192