

INSPECTION REPORT



COMPANY NAME: RAR Cranes Australia Pty Ltd **DATE PRINTED:** 21/03/2022
ADDRESS: 36 Bedford St, Queanbeyan, NSW, 2620. **ACCOUNT NUMBER:** 6765
LOCATION: Unit 481 **SALES ORDER:** 96746
LEAD INSPECTOR: Gary Barreto
SIGNATURE:



Inspection Date	Serial #	Description	Passed	Failed	Missing	Repaired	Condemned	New Into Service	Next Inspection Due
30/08/2019	R9183544	4t x 5m Round Sling	✓					✓	N/A
30/08/2019	R9183550	4t x 5m Round Sling	✓					✓	N/A
30/08/2019	R9183548	4t x 5m Round Sling	✓					✓	N/A
30/08/2019	R9183547	4t x 5m Round Sling	✓					✓	N/A
30/08/2019	R121708536	5t x 4m Round Sling	✓					✓	N/A
30/08/2019	R7174218	5t x 4m Round Sling	✓					✓	N/A
08/03/2020	5-97-98	5t Clutch Lifter	✓						08/03/2021
08/03/2020	6F696	5t Clutch Lifter	✓						08/03/2021



NATA #18983



FIRST FULL MEMBER

LEEA #1192

INSPECTION REPORT



Inspection Date	Serial #	Description	Passed	Failed	Missing	Repaired	Condemned	New Into Service	Next Inspection Due
08/03/2020	RR1	5t Clutch Lifter	✓						08/03/2021
14/03/2022	M1366	10mm x 6m x 2leg G80 Chain Sling Complete With Shorteners & Self Locking Hooks		X			X		14/03/2022
08/03/2020	M1217	10mm x 4m x 2leg G80 Chain Sling Complete With Shorteners & Self Locking Hooks	✓						08/03/2021
14/03/2022	D381	13mm x 4m x 2leg G80 Chain Sling Complete With Shorteners & Self Locking Hooks	✓						14/03/2023
14/03/2022	D1888	13mm x 4m x 2leg G80 Chain Sling Complete With Shorteners & Self Locking Hooks	✓						14/03/2023
14/03/2022	264	8mm x 3m x 2leg G80 Chain Sling Complete With Shorteners & Self Locking Hooks	✓						14/03/2023
07/03/2021	0618-11	2.5t Clutch Lifter	✓						07/03/2022
09/03/2020	RL1607187E	15t Spreader Beam	✓						09/03/2021
14/03/2022	F4862	10mm x 6m x 2leg G80 Chain Sling Complete With Shorteners & Self Locking Hooks	✓						14/03/2023
07/03/2021	844	16mm x 1m x 1leg G80 Chain Sling Complete With Shorteners & Self Locking Hooks	✓						07/03/2022
13/03/2022	RAR8	Container Lifter Left Hand	✓						13/03/2023
07/03/2021	RAR2	Container Lifter Right Hand	✓						07/03/2022
07/03/2021	RAR1	Container Lifter Right Hand	✓						07/03/2022
14/03/2022	150786	3M Spreader Beam 2 Lift Points	✓						14/03/2023



NATA #18983



FIRST FULL MEMBER

LEEA #1192

INSPECTION REPORT



Inspection Date	Serial #	Description	Passed	Failed	Missing	Repaired	Condemned	New Into Service	Next Inspection Due
07/03/2021	8S737	1.3t Clutch Lifter	✓						07/03/2022
07/03/2021	7189-1-454	1.3t Clutch Lifter	✓						07/03/2022



NATA #18983



LEEA #1192