

INSPECTION REPORT



COMPANY NAME: RAR Cranes Australia Pty Ltd **DATE PRINTED:** 21/03/2022
ADDRESS: 36 Bedford St, Queanbeyan, NSW, 2620. **ACCOUNT NUMBER:** 6765
LOCATION: Unit 700 **SALES ORDER:** 107587
LEAD INSPECTOR: Gary Barreto
SIGNATURE:



Inspection Date	Serial #	Description	Passed	Failed	Missing	Repaired	Condemned	New Into Service	Next Inspection Due
13/03/2022	E1644	13mm x 4m x 2leg G80 Chain Sling Complete With Shorteners & Self Locking Hooks	✓						13/03/2023
13/03/2022	D1857	13mm x 4m x 2leg G80 Chain Sling Complete With Shorteners & Self Locking Hooks	✓						13/03/2023
07/03/2021	306	16mm x 6m x 2leg G80 Chain Sling Complete With Shorteners & Self Locking Hooks	✓						07/03/2022
13/03/2022	307	16mm x 6m x 2leg G80 Chain Sling Complete With Shorteners & Self Locking Hooks	✓						13/03/2023
13/03/2022	B1444	16mm x 6m x 2leg G80 Chain Sling Complete With Shorteners & Self Locking Hooks	✓						13/03/2023
14/03/2022	0775.1	12t Spreader Beam	✓						14/03/2023
13/03/2022	RC-3	16mm x 6m x 2leg G80 Chain Sling Complete With Shorteners & Self Locking Hooks	✓						13/03/2023



NATA #18983



FIRST FULL MEMBER

LEEA #1192

INSPECTION REPORT



Inspection Date	Serial #	Description	Passed	Failed	Missing	Repaired	Condemned	New Into Service	Next Inspection Due
13/03/2022	C1817	10mm x 8m x 2leg G80 Chain Sling Complete With Shorteners & Self Locking Hooks	✓						13/03/2023
13/03/2022	1740	10mm x 8m x 2leg G80 Chain Sling Complete With Shorteners & Self Locking Hooks	✓						13/03/2023



NATA #18983



FIRST FULL MEMBER

LEEA #1192