

INSPECTION REPORT



COMPANY NAME: RAR Cranes Australia Pty Ltd **DATE PRINTED:** 21/03/2022
ADDRESS: 36 Bedford St, Queanbeyan, NSW, 2620. **ACCOUNT NUMBER:** 6765
LOCATION: Unit 925 **SALES ORDER:** 107587
LEAD INSPECTOR: Gary Barreto
SIGNATURE:



Inspection Date	Serial #	Description	Passed	Failed	Missing	Repaired	Condemned	New Into Service	Next Inspection Due
13/03/2022	192476	10mm x 6m x 2leg G100 Chain Sling Complete With Shorteners & Self Locking Hooks	✓						13/03/2023
13/03/2022	192477	10mm x 6m x 2leg G100 Chain Sling Complete With Shorteners & Self Locking Hooks	✓						13/03/2023
18/11/2021	E004010080E1EB7D	2m Blue Pole Strap	✓						18/05/2022
01/10/2020	E004010081237912	2m Blue Pole Strap	✓						01/04/2021
18/11/2021	E004010080E227FC	2m Blue Pole Strap	✓						18/05/2022
12/11/2019	P932	10mm x 2m x 2leg G80 Chain Sling Complete With Shorteners & Self Locking Hooks	✓						12/11/2020
13/03/2022	272	13mm x 6m x 2leg G80 Chain Sling Complete With Shorteners & Self Locking Hooks	✓						13/03/2023



NATA #18983



FIRST FULL MEMBER

LEEA #1192

INSPECTION REPORT



Inspection Date	Serial #	Description	Passed	Failed	Missing	Repaired	Condemned	New Into Service	Next Inspection Due
13/03/2022	271	13mm x 6m x 2leg G80 Chain Sling Complete With Shorteners & Self Locking Hooks	✓						13/03/2023
07/03/2021	2010	10mm x 2m x 2leg G80 Chain Sling Complete With Shorteners & Self Locking Hooks	✓						07/03/2022
09/03/2020	PL16021871	15t Spreader Beam	✓						09/03/2021
13/03/2022	7G558	2.5t Clutch Lifter	✓						13/03/2023
13/03/2022	6F92	5t Clutch Lifter	✓						13/03/2023
07/03/2021	PLGT	5t Clutch Lifter	✓						07/03/2022
07/03/2021	3F91	5t Clutch Lifter	✓						07/03/2022
13/03/2022	679	Container Lifter Left Hand	✓						13/03/2023
13/03/2022	677	Container Lifter Right Hand	✓						13/03/2023
13/03/2022	CH-3	Container Lifter Right Hand	✓						13/03/2023
13/03/2022	CH-3	Container Lifter Left Hand	✓						13/03/2023
13/03/2022	PB032	16mm x 300mm x 1leg G100 Chain Sling Complete With Shorteners & Self Locking Hooks	✓						13/03/2023
14/03/2022	1502806	3M Spreader Beam 2 Lift Points	✓						14/03/2023
13/03/2022	5B873	2.5t Clutch Lifter	✓						13/03/2023



NATA #18983



LEEA #1192

INSPECTION REPORT



Inspection Date	Serial #	Description	Passed	Failed	Missing	Repaired	Condemned	New Into Service	Next Inspection Due
13/03/2022	9924	2.5t Clutch Lifter	✓						13/03/2023
13/03/2022	PH0584-11	2.5t Clutch Lifter	✓						13/03/2023
13/03/2022	877	3t Clutch Lifter	✓						13/03/2023
13/03/2022	9F462	5t Clutch Lifter	✓						13/03/2023
13/03/2022	9F473	5t Clutch Lifter	✓						13/03/2023
13/03/2022	3A675	5t Clutch Lifter	✓						13/03/2023
13/03/2022	7E550	2.5t Clutch Lifter		X			X		13/03/2022
13/03/2022	2D428	2.5t Clutch Lifter	✓						13/03/2023
13/03/2022	818	2.5t Clutch Lifter	✓						13/03/2023



NATA #18983



FIRST FULL MEMBER

LEEA #1192