

INSPECTION REPORT



COMPANY NAME: RAR Cranes Australia Pty Ltd **DATE PRINTED:** 21/03/2022
ADDRESS: 36 Bedford St, Queanbeyan, NSW, 2620. **ACCOUNT NUMBER:** 6765
LOCATION: Unit 937 **SALES ORDER:** 96746
LEAD INSPECTOR: Gary Barreto
SIGNATURE:



Inspection Date	Serial #	Description	Passed	Failed	Missing	Repaired	Condemned	New Into Service	Next Inspection Due
30/08/2019	R10160001	8t x 6m Round Sling	✓					✓	N/A
13/03/2022	181321	13mm x 8m x 2 Leg G100 Chain Sling Complete With Shortners And Self Locking Hooks	✓						13/03/2023
14/03/2022	1500831	3m Spreader Beam 2 Lift Points	✓						14/03/2023
13/03/2022	181319	10mm x 8m x 2 Leg G100 Chain Sling Complete With Shortners And Self Locking Hooks	✓						13/03/2023
13/03/2022	181320	13mm x 8m x 2 Leg G100 Chain Sling Complete With Shortners And Self Locking Hooks	✓						13/03/2023



NATA #18983



FIRST FULL MEMBER

LEEA #1192

INSPECTION REPORT



Inspection Date	Serial #	Description	Passed	Failed	Missing	Repaired	Condemned	New Into Service	Next Inspection Due
13/03/2022	181318	10mm x 8m x 2 Leg G100 Chain Sling Complete With Shortners And Self Locking Hooks	✓						13/03/2023



NATA #18983



LEEA #1192