

# INSPECTION REPORT



**COMPANY NAME:** RAR Cranes Australia Pty Ltd **DATE PRINTED:** 21/03/2022  
**ADDRESS:** 36 Bedford St, Queanbeyan, NSW, 2620. **ACCOUNT NUMBER:** 6765  
**LOCATION:** Unit 947 **SALES ORDER:** 103487  
**LEAD INSPECTOR:** Gary Barreto  
**SIGNATURE:**




---

Inspection Date	Serial #	Description	Passed	Failed	Missing	Repaired	Condemned	New Into Service	Next Inspection Due
07/03/2021	B918	10mm x 6m x 2leg G80 Chain Sling Complete With Shorteners & Self Locking Hooks	✓						07/03/2022
07/03/2021	b917	10mm x 6m x 2leg G80 Chain Sling Complete With Shorteners & Self Locking Hooks	✓						07/03/2022
13/03/2022	302	13mm x 6m x 2leg G80 Chain Sling Complete With Shorteners & Self Locking Hooks	✓						13/03/2023
13/03/2022	321	13mm x 8m x 2leg G80 Chain Sling Complete With Shorteners & Self Locking Hooks	✓						13/03/2023
13/03/2022	255	10mm x 4m x 1leg G80 Chain Sling Complete With Shorteners & Self Locking Hooks	✓						13/03/2023
13/03/2022	254	10mm x 4m x 1leg G80 Chain Sling Complete With Shorteners & Self Locking Hooks	✓						13/03/2023
13/03/2022	3380W	10mm x 6.4m x 2leg G80 Chain Sling Complete With Shorteners & Self Locking Hooks	✓						13/03/2023



NATA #18983



FIRST FULL MEMBER

LEEA #1192

# INSPECTION REPORT



Inspection Date	Serial #	Description	Passed	Failed	Missing	Repaired	Condemned	New Into Service	Next Inspection Due
13/03/2022	3381W	10mm x 6.4m x 2leg G80 Chain Sling Complete With Shorteners & Self Locking Hooks	✓						13/03/2023
14/03/2022	0422	12t Spreader Beam	✓						14/03/2023



NATA #18983



FIRST FULL MEMBER

LEEA #1192