

# INSPECTION REPORT



**COMPANY NAME:** RAR Cranes Australia Pty Ltd **DATE PRINTED:** 21/03/2022  
**ADDRESS:** 36 Bedford St, Queanbeyan, NSW, 2620. **ACCOUNT NUMBER:** 6765  
**LOCATION:** Unit 949 **SALES ORDER:** 98785  
**LEAD INSPECTOR:** Gary Barreto  
**SIGNATURE:**

Inspection Date	Serial #	Description	Passed	Failed	Missing	Repaired	Condemned	New Into Service	Next Inspection Due
08/03/2020	4176	5t Clutch Lifter	✓						08/03/2021
13/03/2022	06075-1-2401	1.3t Clutch Lifter	✓						13/03/2023
08/03/2020	RAR4	Container Lifter Left Hand	✓						08/03/2021
13/03/2022	0085	1.3t Clutch Lifter	✓						13/03/2023
08/03/2020	4176	5t Clutch Lifter	✓						08/03/2021
13/03/2022	F3796	16mm x 8m x 2leg G80 Chain Sling Complete With Shorteners & Self Locking Hooks	✓						13/03/2023
07/03/2021	0417	16mm x 6m x 2leg G80 Chain Sling Complete With Shorteners & Self Locking Hooks	✓						07/03/2022



NATA #18983



FIRST FULL MEMBER

LEEA #1192

# INSPECTION REPORT



Inspection Date	Serial #	Description	Passed	Failed	Missing	Repaired	Condemned	New Into Service	Next Inspection Due
13/03/2022	A305	10mm x 6m x 2leg G120 Chain Sling Complete With Shorteners & Self Locking Hooks	✓						13/03/2023
13/03/2022	A306	10mm x 6m x 2leg G120 Chain Sling Complete With Shorteners & Self Locking Hooks	✓						13/03/2023
13/03/2022	B3	Container Lifter Left Hand	✓						13/03/2023
13/03/2022	B4	Container Lifter Left Hand	✓						13/03/2023
13/03/2022	B1	Container Lifter Right Hand	✓						13/03/2023
13/03/2022	B2	Container Lifter Right Hand	✓						13/03/2023
13/03/2022	6G482	2.5t Clutch Lifter	✓						13/03/2023
13/03/2022	5D27	2.5t Clutch Lifter	✓						13/03/2023
13/03/2022	1286	2.5t Clutch Lifter	✓						13/03/2023
13/03/2022	PH348	2.5t Clutch Lifter	✓						13/03/2023
13/03/2022	014	1.3t Clutch Lifter		X			X		13/03/2022
07/03/2021	187	1.3t Clutch Lifter	✓						07/03/2022
14/03/2022	159282-5	3m Spreader Beam 2 Lift Points	✓						14/03/2023
13/03/2022	D417	16mm x 6.5m x 2leg G80 Chain Sling Complete With Shorteners & Self Locking Hooks	✓						13/03/2023
13/03/2022	C168	16mm Multi Heading G100	✓						13/03/2023



NATA #18983



FIRST FULL MEMBER

LEEA #1192

# INSPECTION REPORT



Inspection Date	Serial #	Description	Passed	Failed	Missing	Repaired	Condemned	New Into Service	Next Inspection Due
13/03/2022	183	1.3t Clutch Lifter	✓						13/03/2023
13/03/2022	9F491	5t Clutch Lifter	✓						13/03/2023
13/03/2022	8B482	5t Clutch Lifter	✓						13/03/2023
13/03/2022	4G904	5t Clutch Lifter	✓						13/03/2023
13/03/2022	6F59	5t Clutch Lifter	✓						13/03/2023



NATA #18983



FIRST FULL MEMBER

LEEA #1192