

# INSPECTION REPORT



**COMPANY NAME:** RAR Cranes Australia Pty Ltd **DATE PRINTED:** 21/03/2022  
**ADDRESS:** 36 Bedford St, Queanbeyan, NSW, 2620. **ACCOUNT NUMBER:** 6765  
**LOCATION:** Unit 980 **SALES ORDER:** 107587  
**LEAD INSPECTOR:** Gary Barreto  
**SIGNATURE:**




---

Inspection Date	Serial #	Description	Passed	Failed	Missing	Repaired	Condemned	New Into Service	Next Inspection Due
13/03/2022	19440	10mm x 8m x 2leg G80 Chain Sling Complete with Oversized Heading, Shorteners and Self Locking Hooks	✓						13/03/2023
13/03/2022	19445	10mm x 8m x 2leg G80 Chain Sling Complete with Oversized Heading, Shorteners and Self Locking Hooks	✓						13/03/2023
13/03/2022	6870W	13mm x 8.4m x 2leg G80 Chain Sling Complete With Shorteners & Self Locking Hooks	✓						13/03/2023
13/03/2022	C6.4	13mm x 6.5m x 2leg G80 Chain Sling Complete With Shorteners & Self Locking Hooks	✓						13/03/2023
13/03/2022	ALS1477.1	16mm x 8.5m x 2leg G100 Chain Sling Complete With Shorteners & Self Locking Hooks	✓						13/03/2023



NATA #18983



FIRST FULL MEMBER

LEEA #1192

# INSPECTION REPORT



Inspection Date	Serial #	Description	Passed	Failed	Missing	Repaired	Condemned	New Into Service	Next Inspection Due
13/03/2022	ALS1477.2	16mm x 8.8m x 2leg G100 Chain Sling Complete With Shorteners & Self Locking Hooks	✓						13/03/2023
08/03/2021	156288-05	3m Spreader Beam 2 Lift Points	✓						08/03/2022
13/03/2022	K289	10mm x 0.5m x 1leg G100 Chain Sling Complete With Self Locking Hooks at each end	✓						13/03/2023
13/03/2022	K285	10mm x 0.5m x 1leg G100 Chain Sling Complete With Self Locking Hooks at each end	✓						13/03/2023
13/03/2022	K282	10mm x 0.5m x 1leg G100 Chain Sling Complete With Self Locking Hooks at each end	✓						13/03/2023
13/03/2022	K283	10mm x 0.5m x 1leg G100 Chain Sling Complete With Self Locking Hooks at each end	✓						13/03/2023
14/03/2022	1500425	3M Spreader Beam 2 Lift Points	✓						14/03/2023



NATA #18983



FIRST FULL MEMBER

LEEA #1192