Providing
C CRANE SERVICES.
H HEIGHT SAFETY.
L LIFTING SERVICES.
E ENGINEERING.

Inspection Report

Job No:	23-0116
Page No	
Client Order/Purchase No:	
Date:	Start: 16-Feb-23 Finish: 11-Apr-23
Site:	Multiple

Inspectors
N Thompson NT
D Simpkins DS
A Murphy AM

Dianneil Pty Ltd. t/as CHLE
ABN: 73 619 705 190
PO Box 454, Mitchell, ACT 2911
Ph: (02) 6255 5741
Email: chlesales@chle.com.au

Client name: …
Address:…....
Contact:……
Email:……..
Mob: ……..

RAR CRANES
36 Bedford street
Queanbeyan NSW 2620
Richard Garrety
richard@rargroup.com.au
0405 991 935

NOTE: The Next Inspection Due Date is a Maximum Date Due. The inspection schedule has to be determined by the end user based on the duty cycle (of M3 as specified in AS1418.1) and the environmental conditions of use

Location	Asset	Inspection Date	Serial No	Description	Manufacturer	WLL	Inspected IAW: AS	Passed	Failed	Missing	Repaired	Condemned	Inspector	Next Inspection Due
937		02-Mar-23	181319	G100, 10mm x 8M 2 leg chain sling c/w: eye grab and clevis safety hooks	Ranger	6.9t @ 60°	AS 3775	YES					AM	02-Mar-24
937		02-Mar-23	181318	G100, 10mm x 8M 2 leg chain sling c/w: eye grab and clevis safety hooks	Ranger	6.9t @ 60°	AS 3775	YES					AM	02-Mar-24
937		02-Mar-23	181321	G100, 10mm x 8M 2 leg chain sling c/w: eye grab and clevis safety hooks	Ranger	6.9t @ 60°	AS 3775	YES					AM	02-Mar-24
937		02-Mar-23	181320	G100, 10mm x 8M 2 leg chain sling c/w: eye grab and clevis safety hooks	Ranger	6.9t @ 60°	AS 3775	YES					AM	02-Mar-24