

Providing
C CRANE SERVICES.
H HEIGHT SAFETY.
L LIFTING SERVICES.
E ENGINEERING.

Inspection Report

Job No: 23-0227
 Page No:
 Client Order/Purchase No:
 Date: Start: 14-Jun-23 Finish: 14-Jun-23
 Site: Multiple

Inspectors
 N Thompson NT
 D Simpkins DS
 A Murphy AM

Dianneil Pty Ltd. t/as CHLE
 ABN: 73 619 705 190
 PO Box 454, Mitchell, ACT 2911
 Ph: (02) 6255 5741
 Email: chlesales@chle.com.au

Client name: ...
 Address:.....
 Contact:.....
 Email:.....
 Mob:

RAR CRANES
 36 Bedford street
 Queanbeyan NSW 2620
 Richard Garrety
richard@rargroup.com.au
 0405 991 935

NOTE: The Next Inspection Due Date is a Maximum Date Due. The inspection schedule has to be determined by the end user based on the duty cycle (of M3 as specified in AS1418.1) and the environmental conditions of use

Location	Asset	Inspection Date	Serial No	Description	Manufacturer	WLL	Inspected IAW: AS	Passed	Failed	Missing	Repaired	Condemned	Inspector	Next Inspection Due
Unit 101		11-Apr-23	243	G80, 8mm x3M 2 Leg Chain Sling c/w: eye grab and clevis safety hooks	All Ways Rigging Gear	3.5t @ 60°	AS3775	YES					AM	11-Apr-24
Unit 101		11-Apr-23	070	G80, 8mm x 3M 2 Leg Chain Sling c/w: eye grab and Clevis safety hook	All Ways Rigging Gear	3.5t @ 60°	AS3775	YES					AM	11-Apr-24