



Providing

CRANE SERVICES.

HEIGHT SAFETY.

LIFTING SERVICES.

ENGINEERING.

Inspection Report

Job No:	23-0227
Page No	
Client Order/Purchase No:	
Date:	Start: 14-Jun-23 Finish: 14-Jun-23
Site:	Multiple

<u>Inspectors</u>	
N Thompson	NT
D Simpkins	DS
A Murphy	AM

Dianneil Pty Ltd. t/as CHLE
 ABN: 73 619 705 190
 PO Box 454, Mitchell, ACT 2911
 Ph: (02) 6255 5741
 Email: chlesales@chle.com.au

Client name: ...	RAR CRANES
Address:.....	36 Bedford street Queanbeyan NSW 2620
Contact:.....	Richard Garrety
Email:.....	richard@rargroup.com.au
Mob:	0405 991 935

NOTE: The Next Inspection Due Date is a Maximum Date Due. The inspection schedule has to be determined by the end user based on the duty cycle (of M3 as specified in AS1418.1) and the environmental conditions of use

Location	Asset	Inspection Date	Serial No	Description	Manufacturer	WLL	Inspected IAW: AS	Passed	Failed	Missing	Repaired	Condemned	Inspector	Next Inspection Due
Unit 719		15-May-23	F3789	G80, 8mm x 6M 2 Leg Chain Sling c/w: eye grab and safety hooks	All Ways Rigging Gear	3.5t @ 60°	AS3775	YES					AM	15-May-24