

5/110 STATION ROAD, SEVEN HILLS NSW 2147
Ph: 02 9838 4735 Fax: 02 9838 4710

VISUAL INSPECTION REPORT

| | | | |
|---------------------|--|----------------|--------------|
| Customer | : RAR GROUP | Contact | : PAT |
| Location | : U 949 | Date Inspected | : 03.02.2025 |
| D/D No | : N/A | Report No | : 222183 |
| Report Received by | : pat@rarcrenes.com.au | Customer O/N | : ANNUAL |
| Next Inspection Due | : FEB 2026 | Colour Code | : RED |

This report follows the visual inspection of lifting gear at your facility by Matthew Lovett-Jeans. Inspections were conducted with reference to Company endorsed Work Instructions, Relevant Standards, Occupational Health & Safety requirements and Manufacturers recommendations to determine acceptance / rejection criteria's.

1. AS3776-2006 LIFTING COMPONENTS FOR GRADE T CHAIN
2. AS3775.1-2014 CHAIN SLINGS GRADE T
3. AS4991-2004 LIFTING DEVICES
4. AS2318-2006 SWIVELS FOR LIFTING APPLICATIONS

All items satisfying the above requirements were tagged or hard stamped to cross reference with this report.

Items listed as "R" (Repair) should be quarantined and repaired prior to further use.

Items listed as "F" (Fail) are not suitable for continued use or for their intended purpose and should be destroyed and discarded immediately. We cannot accept any responsibility for continued use

Items listed as "N" (Not Presented) were unable to be located on site.

Items listed as "P" (Pass) are suitable for continued use and can be put back into service. Should any replacement parts be required they can be supplied by reference to the item number of this report.

All items have been fitted with a **RED** colour coded identification tag. We shall contact you early FEBRUARY to arrange your next inspection. Should you require any further information please contact the undersigned.

Yours Truly,



Matthew Lovett-Jeans
Inspection Officer
Email: sydneyinspections@alllifting.com.au
Phone: 02 9838 4735

1300 666 733 • www.alllifting.com.au


Report No:222183

Customer Name: RAR GROUP

Date of Inspection: 03.02.2025

| Item | Identification Number | Description | W.L.L. Or D.O.W | Location | Inspection Date | Inspection Due | Comments | P / F / R / N |
|------|-----------------------|--|---------------------|----------|-----------------|----------------|----------|---------------|
| 1 | F3796 | 16MM GRADE 80 2 LEG ASSEMBLY COMPLETE WITH LARGE MASTER LINK, EYE TYPE GRAB HOOKS AND EYE SELF LOCKING HOOKS AT BASE. 8M | 13.8 TONNE @ 60 DEG | U 949 | 03.02.2025 | FEB 2026 | N/A | Pass |
| 2 | D417 | 16MM GRADE 80 2 LEG ASSEMBLY COMPLETE WITH LARGE MASTER LINK, EYE TYPE GRAB HOOKS AND EYE SELF LOCKING HOOKS AT BASE. 8M | 13.8 TONNE @ 60 DEG | U 949 | 03.02.2025 | FEB 2026 | N/A | Pass |
| 3 | A306 | 10MM GRADE 120 2 LEG ASSEMBLY COMPLETE WITH REGULAR OBLONG, EYE TYPE GRAB HOOKS AND CLEVIS SELF LOCKING HOOKS AT BASE. | 8.45 TONNE @ 60 DEG | U 949 | 03.02.2025 | FEB 2026 | N/A | Pass |
| 4 | K444 | 20-16 GRADE 100 MULI LINK | 17.3 TONNE @ 60 DEG | U 949 | 03.02.2025 | FEB 2026 | N/A | Pass |
| 5 | 159282-05 | FRANNA COMBO BEAM | 15 TONNE | U 949 | 03.02.2025 | FEB 2026 | N/A | Pass |
| 6 | BB40808 | FRANNA HOOK | 25 TONNES | U 949 | 03.02.2025 | FEB 2026 | N/A | Pass |

1300 666 733 • www.allifting.com.au



| | |
|-------------------------|----------|
| Report No:222183 | |
| Repair | |
| Failed | |
| Pass | 6 |
| Not Presented | |
| TOTAL | 6 |