



Full Member



ABN 48 795 006 590

1/177 Power St, Glendenning, NSW, 2761
Phone: (02) 9838 4735



Full Member

VISUAL INSPECTION REPORT

Customer:	RAR CRANES AUSTRALIA	Contact:	ANDREW BODMAN
Location:	CHAINS	Inspection Date:	09/02/2026
D/D No:	N/A	Report No:	258654/UNIT400
Report Received by:	andrewb@rargroup.com.au	Customer O/N:	N/A
Next Inspection Due:	FEBRUARY 2027	Colour Code:	RED

This report follows the visual inspection of lifting gear performed by Hasan Ozbal. Inspections were conducted with reference to Company endorsed Work Instructions, Relevant Standards, Occupational Health & Safety requirements and Manufacturers recommendations to determine acceptance / rejection criteria's.

1. AS 3775.2:2014 Chain slings for lifting purposes - grade T(80) and V(100) product specification
2. AS 3776 :2015 Lifting components for grade T(80) and V(100) chain slings

All items satisfying the above requirements were tagged or hard stamped to cross reference with this report.

Items listed as "R" (Repair) should be quarantined and repaired prior to further use.

Items listed as "F" (Failed) are not suitable for continued use or for their intended purpose and should be destroyed and discarded immediately. We cannot accept any responsibility for continued use.

Items listed as "N" (Not Presented) were unable to be located on site.

Items listed as "P" (Pass) are suitable for continued use and can be put back into service. Should any replacement parts be required they can be supplied by reference to the item number of this report.

All items have been fitted with a RED colour coded identification tag. We shall contact you early February 2027 to arrange your next inspection. Should you require any further information please contact the undersigned.

Yours Truly

Hasan Ozbal
Inspection Officer
Email: hasano@alllifting.com.au
Mobile: 0403 208 495
Phone: (02) 9838 4735

1300 666 733 • www.alllifting.com.au



Full Member



ABN 48 795 006 590

1/177 Power St, Glendenning, NSW, 2761
Phone: (02) 9838 4735

Full Member

Report: 258654/UNIT400

Customer: RAR CRANES AUSTRALIA

Date of Inspection: 09/02/2026

Item	ID Number	Description	W.L.L.	D.O.W.	Location	Insp. Date	Insp. Due	Comments	P/F/R/N
1	19169	CHAIN SLING 10MM 2 LEG GR-100 C/W LARGE MULTI LINK EYE GRAB HOOK/S CLEVIS SELF LOCKING HOOK/S 8MTR	6.9 TONNE @ 60°	N/A	UNIT 400	09/02/2026	02/2027	N/A	Pass
2	19170	CHAIN SLING 10MM 2 LEG GR-100 C/W LARGE MULTI LINK EYE GRAB HOOK/S CLEVIS SELF LOCKING HOOK/S 8MTR	6.9 TONNE @ 60°	N/A	UNIT 400	09/02/2026	02/2027	N/A	Pass
3	1	CHAIN SLING 10MM CHEATER CHAINS WITH SELF LOCKING HOOK EACH END GR-100 C/W	4 TONNE	N/A	UNIT 400	09/02/2026	02/2027	N/A	Pass
4	2	CHAIN SLING 10MM CHEATER CHAINS WITH SELF LOCKING HOOK EACH END GR-100 C/W	4 TONNE	N/A	UNIT 400	09/02/2026	02/2027	N/A	Pass
5	3	CHAIN SLING 10MM CHEATER CHAINS WITH SELF LOCKING HOOK EACH END GR-100 C/W	4 TONNE	N/A	UNIT 400	09/02/2026	02/2027	N/A	Pass
6	4	CHAIN SLING 10MM CHEATER CHAINS WITH SELF LOCKING HOOK EACH END GR-100 C/W	4 TONNE	N/A	UNIT 400	09/02/2026	02/2027	N/A	Pass
7	2210	CHAIN SLING 10MM INLINE SHORTNER 17 LINKS GR-80 C/W	3.2 TONNE	N/A	UNIT 400	09/02/2026	02/2027	N/A	Pass
8	P561	CHAIN SLING 10MM INLINE SHORTNER 17 LINKS GR-80 C/W	3.2 TONNE	N/A	UNIT 400	09/02/2026	02/2027	N/A	Pass
9	P563	CHAIN SLING 10MM INLINE SHORTNER 17 LINKS GR-80 C/W	3.2 TONNE	N/A	UNIT 400	09/02/2026	02/2027	N/A	Pass
10	24688	CHAIN SLING 13MM 2 LEG GR-100 C/W OBLONG LINK EYE GRAB HOOK/S CLEVIS SELF LOCKING HOOK/S 6MTR	11.2 TONNE @ 60°	N/A	UNIT 400	09/02/2026	02/2027	N/A	Pass
11	24689	CHAIN SLING 13MM 2 LEG GR-100 C/W OBLONG LINK EYE GRAB HOOK/S CLEVIS SELF LOCKING HOOK/S 6MTR	11.2 TONNE @ 60°	N/A	UNIT 400	09/02/2026	02/2027	N/A	Pass
12	19321	CHAIN SLING 13MM INLINE SHORTNER 5 LINKS GR-100 C/W	6.7 TONNE	N/A	UNIT 400	09/02/2026	02/2027	N/A	Pass
13	19322	CHAIN SLING 13MM INLINE SHORTNER 5 LINKS GR-100 C/W	6.7 TONNE	N/A	UNIT 400	09/02/2026	02/2027	N/A	Pass
14	400.1	CHAIN SLING 16MM 2 LEG GR-100 C/W MULTI HEAD RING CLEVIS GRAB HOOK/S CLEVIS SELF LOCKING HOOK/S 8MTR	17.3 TONNE @ 60°	N/A	UNIT 400	09/02/2026	02/2027	N/A	Pass
15	400.2	CHAIN SLING 16MM 2 LEG GR-100 C/W MULTI HEAD RING CLEVIS GRAB HOOK/S CLEVIS SELF LOCKING HOOK/S 8MTR	17.3 TONNE @ 60°	N/A	UNIT 400	09/02/2026	02/2027	TAG REPLACED	Pass
16	K9	LIFTING COMPONENT OBLONG LINK 26-32 GR-80	36.7 TONNE @ 60°	N/A	UNIT 400	09/02/2026	02/2027	N/A	Pass
17	K9	LIFTING COMPONENT OBLONG LINK 26-32 GR-80	36.7 TONNE @ 60°	N/A	UNIT 400	09/02/2026	02/2027	N/A	Pass

1300 666 733 • www.alllifting.com.au



Full Member



ABN 48 795 006 590


1/177 Power St, Glendenning, NSW, 2761
Phone: (02) 9838 4735



Full Member

Inspection Chart

Repair Fail No Presented Pass



Report No	258654/UNIT400
Repair	0
Not Presented	0
Pass	17
Failed	0
TOTAL	17

1300 666 733 • www.alllifting.com.au