



Full Member



ABN 48 795 006 590

1/177 Power St, Glendenning, NSW, 2761
Phone: (02) 9838 4735



Full Member

VISUAL INSPECTION REPORT

Customer:	RAR CRANES AUSTRALIA	Contact:	JAMES S
Location:	UNIT 941	Inspection Date:	09/02/2026
D/D No:	N/A	Report No:	258654 / UNIT 941
Report Received by:	andrewb@rargroup.com.au	Customer O/N:	N/A
Next Inspection Due:	FEBRUARY 2027	Colour Code:	RED

This report follows the visual inspection of lifting gear performed by Hasan Ozbal. Inspections were conducted with reference to Company endorsed Work Instructions, Relevant Standards, Occupational Health & Safety requirements and Manufacturers recommendations to determine acceptance / rejection criteria's.

1. AS 3775.2:2014 Chain slings for lifting purposes - grade T(80) and V(100) product specification
2. AS 3850.1 Clause 2.6 Prefabricated concrete elements general requirements
3. AS 3776 :2015 Lifting components for grade T(80) and V(100) chain slings
4. AS 4991-2004 Lifting Devices

All items satisfying the above requirements were tagged or hard stamped to cross reference with this report.

Items listed as "R" (Repair) should be quarantined and repaired prior to further use.

Items listed as "F" (Failed) are not suitable for continued use or for their intended purpose and should be destroyed and discarded immediately. We cannot accept any responsibility for continued use.

Items listed as "N" (Not Presented) were unable to be located on site.

Items listed as "P" (Pass) are suitable for continued use and can be put back into service. Should any replacement parts be required they can be supplied by reference to the item number of this report.

All items have been fitted with a RED colour coded identification tag. We shall contact you early February 2027 to arrange your next inspection. Should you require any further information please contact the undersigned.

Yours Truly

Hasan Ozbal
Inspection Officer
Email: hasano@alllifting.com.au
Mobile: 0403 208 495
Phone: (02) 9838 4735

1300 666 733 • www.alllifting.com.au



Full Member



ABN 48 795 006 590

1/177 Power St, Glendenning, NSW, 2761
Phone: (02) 9838 4735



Full Member

Report: 258654 / UNIT 941

Customer: RAR CRANES AUSTRALIA

Date of Inspection: 09/02/2026

Item	ID Number	Description	W.L.L.	D.O.W.	Location	Insp. Date	Insp. Due	Comments	P/F/R/N
1	P2022	CHAIN SLING 10MM 2 LEG GR-100 C/W REGULAR MULTI LINK EYE GRAB HOOK/S CLEVIS SELF LOCKING HOOK/S 8MTR	6.9 TONNE @ 60°	N/A	UNIT 941	09/02/2026	02/2027	N/A	Pass
2	P2097	CHAIN SLING 10MM 2 LEG GR-100 C/W REGULAR MULTI LINK EYE GRAB HOOK/S CLEVIS SELF LOCKING HOOK/S 8MTR	6.9 TONNE @ 60°	N/A	UNIT 941	09/02/2026	02/2027	N/A	Pass
3	729	CHAIN SLING 10MM 2 LEG GR-80 C/W REGULAR OBLONG LINK CLEVIS GRAB HOOK/S CLEVIS SELF LOCKING HOOK/S	5.5 TONNE @ 60°	N/A	UNIT 941	09/02/2026	02/2027	N/A	Pass
4	3613Y	CHAIN SLING 13MM 2 LEG GR-100 C/W REGULAR OBLONG LINK CLEVIS GRAB HOOK/S CLEVIS SELF LOCKING HOOK/S	6.9 TONNE @ 60°	N/A	UNIT 941	09/02/2026	02/2027	N/A	Pass
5	3614Y	CHAIN SLING 13MM 2 LEG GR-100 C/W REGULAR OBLONG LINK CLEVIS GRAB HOOK/S CLEVIS SELF LOCKING HOOK/S	6.9 TONNE @ 60°	N/A	UNIT 941	09/02/2026	02/2027	N/A	Pass
6	844	CHAIN SLING 16MM 1 LEG GR-80 C/W OBLONG LINK CLEVIS SELF LOCKING HOOK/S 2MTR	8 TONNE	N/A	UNIT 941	09/02/2026	02/2027	N/A	Pass
7	6A 270	CONCRETE CLUTCH MUSHROOM TYPE	5 TONNE	N/A	UNIT 941	09/02/2026	02/2027	N/A	Pass
8	6A 270	CONCRETE CLUTCH MUSHROOM TYPE - REID	5 TONNE	N/A	UNIT 941	09/02/2026	02/2027	N/A	Pass
9	6F 696	CONCRETE CLUTCH MUSHROOM TYPE - REID	5 TONNE	N/A	UNIT 941	09/02/2026	02/2027	N/A	Pass
10	6F 712	CONCRETE CLUTCH MUSHROOM TYPE - REID	5 TONNE	N/A	UNIT 941	09/02/2026	02/2027	N/A	Pass
11	7A 486	CONCRETE CLUTCH MUSHROOM TYPE - REID	5 TONNE	N/A	UNIT 941	09/02/2026	02/2027	N/A	Pass
12	LM114	CONCRETE CLUTCH RING TYPE - PSA	10 TONNE	N/A	UNIT 941	09/02/2026	02/2027	N/A	Pass
13	2101	CONTAINER HOOK LEFT	12.5 TONNE PER PAIR	N/A	UNIT 941	09/02/2026	02/2027	N/A	Pass
14	2101	CONTAINER HOOK LEFT	12.5 TONNE PER PAIR	N/A	UNIT 941	09/02/2026	02/2027	N/A	Pass
15	2101	CONTAINER HOOK RIGHT	12.5 TONNE PER PAIR	N/A	UNIT 941	09/02/2026	02/2027	N/A	Pass
16	2101	CONTAINER HOOK RIGHT	12.5 TONNE PER PAIR	N/A	UNIT 941	09/02/2026	02/2027	N/A	Pass
17	BB37225	LIFTING DEVICE FRANNA HOOK	14 TONNE	N/A	UNIT 941	09/02/2026	02/2027	N/A	Pass

1300 666 733 • www.alllifting.com.au



Full Member



ABN 48 795 006 590


1/177 Power St, Glendenning, NSW, 2761
Phone: (02) 9838 4735



Full Member

Inspection Chart

Repair Fail No Presented Pass



Report No	258654 / UNIT 941
Repair	0
Not Presented	0
Pass	17
Failed	0
TOTAL	17

1300 666 733 • www.alllifting.com.au