



Full Member



ABN 48 795 006 590

1/177 Power St, Glendenning, NSW, 2761
Phone: (02) 9838 4735



Full Member

VISUAL INSPECTION REPORT

Customer: RAR CRANES AUSTRALIA
Location: UNIT 947
D/D No: N/A
Report Received by: andrewb@rargroup.com.au
Next Inspection Due: FEBRUARY 2027

Contact: JAMES S
Inspection Date: 09/02/2026
Report No: 258654 / UNIT 947
Customer O/N: N/A
Colour Code: RED

This report follows the visual inspection of lifting gear performed by Hasan Ozbal. Inspections were conducted with reference to Company endorsed Work Instructions, Relevant Standards, Occupational Health & Safety requirements and Manufacturers recommendations to determine acceptance / rejection criteria's.

1. AS 3775.2:2014 Chain slings for lifting purposes - grade T(80) and V(100) product specification

All items satisfying the above requirements were tagged or hard stamped to cross reference with this report.

Items listed as "R" (Repair) should be quarantined and repaired prior to further use.

Items listed as "F" (Failed) are not suitable for continued use or for their intended purpose and should be destroyed and discarded immediately. We cannot accept any responsibility for continued use.

Items listed as "N" (Not Presented) were unable to be located on site.

Items listed as "P" (Pass) are suitable for continued use and can be put back into service. Should any replacement parts be required they can be supplied by reference to the item number of this report.

All items have been fitted with a RED colour coded identification tag. We shall contact you early February 2027 to arrange your next inspection. Should you require any further information please contact the undersigned.

Yours Truly

Hasan Ozbal
Inspection Officer
Email: hasano@alllifting.com.au
Mobile: 0403 208 495
Phone: (02) 9838 4735



Full Member



ABN 48 795 006 590

1/177 Power St, Glendenning, NSW, 2761
Phone: (02) 9838 4735



Full Member

Report: 258654 / UNIT 947

Customer: RAR CRANES AUSTRALIA

Date of Inspection: 09/02/2026

Item	ID Number	Description	W.L.L.	D.O.W.	Location	Insp. Date	Insp. Due	Comments	P/F/R/N
1	J899	CHAIN SLING 10MM 2 LEG GR-100 C/W LARGE MULTI LINK EYE GRAB HOOK/S CLEVIS SELF LOCKING HOOK/S 8MTR	6.9 TONNE @ 60°	N/A	UNIT 947	09/02/2026	02/2027	N/A	Pass
2	J900	CHAIN SLING 10MM 2 LEG GR-100 C/W LARGE MULTI LINK EYE GRAB HOOK/S CLEVIS SELF LOCKING HOOK/S 8MTR	6.9 TONNE @ 60°	N/A	UNIT 947	09/02/2026	02/2027	N/A	Pass
3	F4591	CHAIN SLING 13MM 2 LEG GR-80 C/W OBLONG LINK EYE GRAB HOOK/S CLEVIS SELF LOCKING HOOK/S 8MTR	9.2 TONNE @ 60°	N/A	UNIT 947	09/02/2026	02/2027	N/A	Pass

1300 666 733 • www.alllifting.com.au



Full Member



ABN 48 795 006 590


1/177 Power St, Glendenning, NSW, 2761
Phone: (02) 9838 4735



Full Member

Inspection Chart

Repair Fail No Presented Pass



Report No	258654 / UNIT 947
Repair	0
Not Presented	0
Pass	3
Failed	0
TOTAL	3

1300 666 733 • www.alllifting.com.au